


PART-II
(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated 28/06/2023 And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used) 31/03/2025



Sub Divisional Engineer,
Ludhiana.

ਪਿੱਠ ਅੰਕਣ ਨੰ. 178

ਮਿਤੀ: 28/6/23

1. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ Shri Guru Ram Rai Sr. Sec. Public School Ferozepur Road, Barewal, Ludhiana ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ. 1, ਲੇ.ਨਿ.ਵਿ., ਭ ਤੇ ਮ ਸਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


Sub Divisional Engineer,
Ludhiana.